

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



1.



2.

2006 CARVER 56 VOYAGER PHOTOGRAPHS




3.



4. Port engine

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**




5. Port gear




6. Starboard engine

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**




7. Starboard gear




8. Oil leak at oil pan gasket, port engine

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



9. Leaking raw water pump at generator




10. Cover removed from water heater panel

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



11. Standing water from apparent leak at water heater shelf



12. Loose fittings at starboard waste tank

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**




13. Generator seastrainer fouled




14. Starboard engine oil pan gasket leak

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**




15. Apparent leak at starboard turbo



16. Overheating damage to wire loom, aft of starboard muffler

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**




17. Overheating damage to battery cable, aft of starboard muffler




18. Overheating damage

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



19. Corroding clamps at starboard exhaust thru-hull connections



20. Overheating damage to wiring at starboard aft lazarette

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



21. Overheating damage to wiring at starboard aft lazarette



22. Broken clamp, corroded fittings, and leaks at air conditioner raw water intake

2006 CARVER 56 VOYAGER
PHOTOGRAPHS




23. Air conditioner sea strainer fouled



24. Trim tab fluid low

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



25. Corrosion at junction box in aft lazarette



26. Corrosion at junction box in aft lazarette

2006 CARVER 56 VOYAGER
PHOTOGRAPHS



27. Wet moisture readings at inboard transom



28. Steering fluid leak

2006 CARVER 56 VOYAGER
PHOTOGRAPHS



29. Damaged wiring from prior overheating



30.

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



31. Swim platform hydraulic fittings corroding




32. Broken and corroded clamps at generator exhaust in port lazarette

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**




33. Corroded clamps at port exhaust fitting at port lazarette



34. Fuel fill hose cracking

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



35. Corrosion at swim platform hydraulic pump




36. Galley drawer does not shut

2006 CARVER 56 VOYAGER PHOTOGRAPHS



37. Wear/discoloration at brightwork/wood at starboard saloon



38. Power available light inoperable

2006 CARVER 56 VOYAGER PHOTOGRAPHS



39. Ammeter not operable



40. Lights inoperable at lounge

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



41. Debris in forward bilge




42. Forward limber hole fouled, centerline

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



43.



44. Aft sundeck railing removed at companionway

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



45. Antenna weathered and worn



46. Fuel cap O-ring worn

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



47. Shore power inlets



48. Shore water connection

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



49. Arc damage to shore cable



50.

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



51.



52.

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**




53.



54.

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



55.



56.

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



57.



58.

**2006 CARVER 56 VOYAGER
PHOTOGRAPHS**



59.



60.